



# VSD Analysis Report

Criteria: SF\_MM\_PC  
Name: M42L01-38

Date: Fri Aug 19 2022  
Time: 15:03:34



Input Image



Analysis Image

**FAIL**

## Analysis Results

	Size Range	Num Allowed	Num Found	Num > Max	Size Range	Num Allowed	Num Found	Num > Max
	DEFECT				SCRATCH			
Zone A 0 - 65 um	0 to 5(um)	4	17	0	0 to 3(um)	Any	1	0
Zone B 65 - 115 um	5 to 10(um)	5	2	1	0 to 5(um)	Any	2	0
Zone C 115 - 135 um	N/A							
Zone D 135 - 250 um	20 to 30(um)	5	0	0	Any	Any	0	0